

From: [Azhar, Wardah](#)
To: [Zhen, Davis](#); [Sheldrake, Sean](#)
Cc: [Scott Coffey](#); younghs@cdmsmith.com
Subject: Re: Coring oversight photos 7/30
Date: Monday, July 30, 2018 3:00:03 PM
Attachments: [image1.jpeg](#)
[image1.jpeg](#)

Cutting core using pipe cutter



On Jul 30, 2018, at 12:02 PM, Azhar, Wardah <azharw@cdmsmith.com> wrote:

Buoys attached to keep the core tube vertical when penetrating.

<image1.jpeg>

On Jul 30, 2018, at 8:44 AM, Azhar, Wardah <azharw@cdmsmith.com> wrote:

Photo of Teiton GPS check in progress

<image1.jpeg>

Photo of poles collapsed and strapped down for boat to travel safely
at speed and under bridges

<image2.jpeg>

Wardah